



- Photo 1 –



- Photo 2 – Oil stained soil in west wall of the excavation east of the separator



- Photo 3 – Close-up of oil stained soil in west wall of the excavation east of the separator



- Photo 4 – Close-up of oil stained soil in west wall of the excavation east of the separator



- Photo 5 – Eastern area of groundwater test pits