

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 1. Battery sign at entrance incomplete.



Inspection Photos
Location Name: Rabbit Ears 0680 23
Location ID: 449274




Photo 2. Inaccurate/incomplete tank labels.



Photo 3. Incomplete wellhead sign.