

**Inspection Photos**  
**Location Name: Surprise Central Facility**  
**Location ID: 436676**



**Photo 1. Sign at one entrance inaccurate/incomplete.**



Inspection Photos  
Location Name: Surprise Central Facility  
Location ID: 436676



Photo 2. Sign at one entrance incomplete.



Photo 3. Battery signs incomplete/inaccurate.






**Inspection Photos**  
**Location Name: Surprise Central Facility**  
**Location ID: 436676**



**Photo 4. Location sign incomplete/inaccurate.**



**Photo 5. Tank label inaccurate.**

