

Inspection Photos
Location Name: Dutch Lake 24-22H
Location ID: 430123



Photo 1 – Wellhead – Unmarked Riser

Photo 2 – Unmarked Riser south of Wellhead

Inspection Photos
Location Name: Dutch Lake 24-22H
Location ID: 430123



Photo 3 – Tank Battery Sign

Photo 4 – Tank Battery

Inspection Photos
Location Name: Dutch Lake 24-22H
Location ID: 430123



Photo 5 – Unmarked Risers

Photo 6 – Marker no longer Valid

Inspection Photos
Location Name: Dutch Lake 24-22H
Location ID: 430123



Photo 7 – Marked no longer valid

Photo 8 – Marker no longer Valid

Inspection Photos
Location Name: Dutch Lake 24-22H
Location ID: 430123




Photo 9 – Unmarked Riser

Photo 10 – Unmarked at ECD

Inspection Photos
Location Name: Dutch Lake 24-22H
Location ID: 430123




Photo 11 – Unmarked Riser at Tanks

Photo 12 – Unmarked at Tanks

Inspection Photos
Location Name: Dutch Lake 24-22H
Location ID: 430123




Photo 13 – Unmarked Riser at Tanks