

# Interim Reclamation and Stormwater Inspection

May 19, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 306149

Inspection Document #: 697502935

Weld County, CO

SESW Section 26 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Kodak South FD Pad /28-222HN

Location ID: 306149



**Photo 1.** 2019 aerial imagery illustrates the total disturbance area. Operator has not performed interim reclamation activities- refer to the following photos.



Inspection Photos

Location Name: Kodak South FD Pad /28-222HN

Location ID: 306149



**Photo 2.** Photo taken from the northern location, facing North. Photo illustrates the storage of a trailer on location.



**Photo 3.** Photo taken from the southeastern location, facing West. Photo illustrates the storage of supplies.



## Inspection Photos

Location Name: Kodak South FD Pad /28-222HN

Location ID: 306149



**Photo 4.** Photo taken from the eastern location, facing South. Photo illustrates weed establishment on the topsoil stockpile.



**Photo 5.** Photo taken from the northeastern location. Photo illustrates a List B Colorado noxious weed, Canada thistle. This was observed throughout the location, including the topsoil stockpile.



## Inspection Photos

Location Name: Kodak South FD Pad /28-222HN

Location ID: 306149



**Photo 6.** Photo taken from the topsoil stockpile. Photo illustrates a List B Colorado noxious weed, Scotch thistle.



**Photo 7.** Photo taken from the southern location, facing South. Photo illustrates the north-facing topsoil stockpile is vegetated with cereal rye but not the remainder.

