

**Inspection Photos**  
**Location Name: Walker 12-1**  
**Location ID: 313132**



**Photo 1. Overview of location taken facing north. Dried annual weeds on location.**



**Photo 2. No bradenhead access apparent.**

