

Inspection Photos
Location Name: Walker 12-5
Location ID: 313149



Photo 1. Overview of location taken facing northeast.



Photo 2. No bradenhead access apparent.

