

Interim Reclamation and Stormwater Inspection

May 20, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 460375

Inspection Document #: 697502939

Adams County, CO

NENE Section 2 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Baseline LE Pad

Location ID: 460375



Photo 1. 2019 aerial imagery illustrates the total disturbance area. Operator has not performed interim reclamation activities- refer to the following photos. Note: Operator indicated they are coordinating with Butterfly Pavilion on a project.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502939

Inspection Photos
Location Name: Baseline LE Pad
Location ID: 460375



Photo 2. Photo taken from the entrance of location, facing South. Photo illustrates a mailbox for the purposes of storing permits; however, no permits were present.



Photo 3. See comments under Photo 2.



Inspection Photos
Location Name: Baseline LE Pad
Location ID: 460375



Photo 4. Photo taken from the eastern access road, facing North. Photo illustrates a List B Colorado noxious weed, Scotch thistle, establishment throughout the entire access road.



Photo 5. Photo taken from the northern location, facing East. Photo illustrates a List B Colorado noxious weed, Scotch thistle, which appears to be spreading off location. Operator shall control and manage what has spread off location, in addition to what is on location.



Inspection Photos
Location Name: Baseline LE Pad
Location ID: 460375



Photo 6. Photo taken from the entrance of location, facing North. Photo illustrates the vehicle tracking device BMP is in need of maintenance.



Photo 7. Photo taken from the northern berm, facing West. Photo illustrates the desirable vegetation is establishing; however, noxious weeds were observed throughout the entire berm.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502939

Inspection Photos
Location Name: Baseline LE Pad
Location ID: 460375



Photo 8. Photo taken from the northern berm. Photo illustrates a List B Colorado noxious weed, Musk thistle.



Photo 9. Photo taken from the northern berm, facing West. Photo illustrates a List B Colorado noxious weed, Scotch thistle.

Inspection Photos
Location Name: Baseline LE Pad
Location ID: 460375



Photo 10. Photo taken from the northern berm, facing Southwest. Photo illustrates Operator has not yet performed interim reclamation and claims the ~12.5' perimeter berm is permanent.



Photo 11. Photo taken from the northern berm, facing South. See comments under Photo 10.

