

Inspection Photos

API# 081-06583

Operator: GRMR

Insp#: 692403402

Insp Date: 5/14/2021





Photo#1:
View over Location from South drive trough entry to North.

May 14, 2021



Photo#2:
North cut slope vegetation



Photo#3:
East cut slope vegetation

May 14, 2021



Photo#4:
West side road fill slope, view to North.

Photo#5:
West side road fill slope, view to South.

May 14, 2021