

Inspection Photos

Location Name: LARAMIE ENERGY LLC Esperanza Ranch /2 Pad

Location ID: 312689



Photo #3948 from entrance to location.



Photo #3949 No battery sign located at the tank battery.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Esperanza Ranch /2 Pad

Location ID: 312689



Photo #3950 Location lacks stabilization.



Photo #3951 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Esperanza Ranch /2 Pad

Location ID: 312689



Photo #3952 No form of tracking BMP located at entrance to location.