

Inspection Photos

Location Name: LARAMIE ENERGY LLC My Way Ranch /18-1 Pad

Location ID: 334412



Photo #3953 from entrance to location.



Photo #3954 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC My Way Ranch /18-1 Pad

Location ID: 334412



Photo #3955 No battery sign located at the tank battery.



Photo #3956 Location lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC My Way Ranch /18-1 Pad

Location ID: 334412



Photo #3957 Location lacks stabilization.



Photo #3958 No form of tracking BMP located at the entrance to location.