

Inspection Photos  
Location Name: Anderson 22-32  
Location ID: 328576



Photo 1 WH sign




Photo 2 WH

**Inspection Photos**  
**Location Name: Anderson 22-32**  
**Location ID: 328576**



**Photo 3 WH appears to have a leak**



**Photo 4 WH appears to have a leak**



**Inspection Photos**  
**Location Name: Anderson 22-32**  
**Location ID: 328576**



**Photo 5 Bradenhead appears to have a leak from the riser**

**Photo 6 Bradenhead appears to have a leak from riser**