

Inspection Photos
Operator: Simcoe
API: 067-06644
Date: 5/24/2021



Photo 1. View of project area from well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass, alfalfa, and smooth brome.



Photos 3. View of the northern project area from the northeastern corner facing westward.



Photos 4. View of dense musk thistles observed near the well pad entrance. Approximately 50 individuals observed.



Photo 5. View of reference area comprised of irrigated crop field with alfalfa at this time.