

Inspection Photos  
Operator: Simcoe  
API: 067-06482  
Date: 5/24/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing in with western wheatgrass, sagebrush, and rubber rabbitbrush.



Photos 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of open gambel oak shrubland, black sagebrush and western wheatgrass shrubland mosaic with mat penstemon, prickly phlox, and squirreltail.