

# Interim Reclamation and Stormwater Inspection

May 20, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 459907

Inspection Document #: 697502943

Adams County, CO

SWNW Section 21 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: TOWER LD PAD  
Location ID: 459907



**Photo 1.** Photo taken from the southern location, facing East. Photo illustrates a ditch BMP along the perimeter with the cut slope to the interior.



**Photo 2.** Photo taken from the southern location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: TOWER LD PAD  
Location ID: 459907



**Photo 3.** Photo taken from the southern location. Photo illustrates a List B Colorado noxious weed, Scotch thistle.



**Photo 4.** Photo taken from the southwestern location, facing North. See comments under Photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697502943



Inspection Photos  
Location Name: TOWER LD PAD  
Location ID: 459907



**Photo 5.** Photo taken from the northwestern location, facing South. Photo illustrates a path of erosion.



**Photo 6.** Photo taken from the northwestern location, facing East. See comments under Photo 5.



Inspection Photos  
Location Name: TOWER LD PAD  
Location ID: 459907



**Photo 7.** Photo taken from the northwestern location, facing North. Photo illustrates sediment has filled up the check dam and is discharging sediment offsite.



**Photo 8.** Photo taken from the topsoil stockpile, facing East. There was some evidence of germination but Operator plans to reseed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697502943



Inspection Photos  
Location Name: TOWER LD PAD  
Location ID: 459907



**Photo 9.** Photo taken from the northwestern location, facing West. Photo illustrates a patch of List B Colorado noxious weeds.



**Photo 10.** Photo taken from the northern location, facing East. Photo illustrates a sediment trap in need of maintenance.



Inspection Photos  
Location Name: TOWER LD PAD  
Location ID: 459907



**Photo 11.** Photo taken from the northeastern location, facing South. Photo illustrates a stabilized channel with check dams and appears maintenance is required along the upslope portion.



**Photo 12.** Photo taken from the northeastern location, facing East. Photo illustrates a sediment trap in need of maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697502943