

Inspection Photos

ID: 307864

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/28/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing toward the ephemeral creek crossing where recent flood event has wash out the cement crossing area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 307864 | Date: 5/28/2021

Inspection Photos



Photo 2. Drone aerial photo facing northeast down the canyon which shows the extent of flooding damage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 307864 | Date: 5/28/2021

Inspection Photos



Photo 3. Drone aerial photo facing toward the ephemeral creek crossing where recent flood event has wash out the cement crossing area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 307864 | Date: 5/28/2021