

Inspection Photos
Location Name: Amelia 44-1
Location ID: 313326



Photo 1. Overview of location taken facing northwest.



Inspection Photos
Location Name: Amelia 44-1
Location ID: 313326



Photo 2. No bradenhead access apparent.



Photo 3. Noxious weeds on access road.