


Inspection Photos
Location Name: Minor 1
Location ID: 322712



Jun 1, 2021 at 11:16:38 AM
 +40.3357,-104.5059
 Weld

Colorado Oil & Gas Conservation Commission



Legals		
Date	Orifice Size	Test Date
1/11/16	1.250	4/1/16 KC
8-3-16	1.000	8-3-16 122
5/5/17	1.000	5/5/17

Jun 1, 2021 at 11:17:41 AM
 +40.3361,-104.5056
 Weld

Colorado Oil & Gas Conservation Commission

Photo #1 Location

Photo #2 Gas Meter will need to be calibrated prior to returning to production.