


**Inspection Photos**  
**Location Name: 1-4N-64W NESW Amigo Farms TB**  
**Facility ID: 479883**



**Photo #1 Repaired berms**



**Photo #2 Gas meter run will need to be calibrated before location returns to production.**