

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2021

Submitted Date:

06/01/2021

Document Number:

699103764

**FIELD INSPECTION FORM**

Loc ID 329753 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249988	WELL	TA	05/29/2020	OW	123-17791	STATE 16-314	TA

**General Comment:**

This is a follow up to FIRR #402699127. CA's have been corrected.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	<input type="text" value="Gas Meter will need calibrated before returning to production."/>		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 249988 Type: WELL API Number: 123-17791 Status: TA Insp. Status: TA**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: T/A

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/02/2019 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: \_\_\_\_\_End Surf Csg Pressure: --Comment: No updated annual bradenhead test on file. Submit Reports.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On Tuesday 6/1/21 at approximately 0850hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR inspection document #402699127 at State 16-314 of Noble Energy, at Location ID# 329753 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules.  See attached photos.  This is a summary of inspection report.</p>	burnsa	06/01/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103765	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444442">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444442</a>