

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/01/2021

Submitted Date:

06/01/2021

Document Number:

699103770

FIELD INSPECTION FORM
 Loc ID 479882 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------------|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|-----------------|--------|-------------|------------|---------|---------------------------------|-------------|
| 479883 | TANK BATTERY | AC | 05/03/2021 | | - | 1-4N-64W NESW Amigo Farms TB | SI |

General Comment:

This is a follow up to FIRR #402699150. CA's have been corrected.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

#

Comment: Gas meter run will need to be calibrated before location goes back to production.

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 479883 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday 6/1/21 at approximately 1143hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR inspection document #402699150 at 1-4N-64W NESW Amigo Farms TB of Noble Energy, at Facility ID# 479883 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules.</p> <p>Gas meter run will need to be calibrated before location goes back to production. See attached photos.</p> <p>This is a summary of inspection report.</p> | burnsa | 06/01/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 699103771 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444445 |