

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



**Photo 1. Overview of location taken facing northwest.
Equipment stored on location.**



Photo 2. Stained soil at wellhead. Hissing leak at wellhead.



Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 3. Tank label peeling.



Photo 4. Example of equipment stored on location.



Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 5. Example of equipment stored on location.



Photo 6. Example of equipment stored on location.



Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 7. Example of equipment stored on location.



Photo 8. Example of equipment stored on location.

