

Inspection Photos
Location Name: South Lost Creek 8
Location ID: 332212



Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: South Lost Creek 8
Location ID: 332212




Photo 3 – Wellhead

Photo 4 – Separator and Gas Meter

Inspection Photos
Location Name: South Lost Creek 8
Location ID: 332212



Photo 5 – Debris from Shed

Photo 6 – Debris from Shed

Inspection Photos
Location Name: South Lost Creek 8
Location ID: 332212



Photo 7 – Debris from Shed