

Final Reclamation Inspection

May 25, 2021

Operator: CONFLUENCE DJ LLC - #10518

Location ID: 320347

Inspection Document #: 697502959

Adams County, CO

SWSE Section 9 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KALLSEN #A-1
Location ID: 320347



Photo 1. Photo taken from the well location, facing East. Photo illustrates the well location is not reflective of reference areas and a List B Colorado noxious weed, Scotch thistle, is spreading off location, in addition to other undesirable plant species. Also, the well location has not been properly recontoured to the surrounding area.

Inspection Photos
Location Name: KALLSEN #A-1
Location ID: 320347



Photo 2. Photo taken from the well location, facing Southeast.
See comments under Photo 1.



Photo 3. Photo taken from the well location, facing Northeast.
See comments under Photo 1.

Inspection Photos
Location Name: KALLSEN #A-1
Location ID: 320347



Photo 4. Photo taken from the associated offsite tank battery location, facing East. Photo illustrates not all equipment has been removed and final reclamation activities have not been performed.

Inspection Photos
Location Name: KALLSEN #A-1
Location ID: 320347



Photo 5. Photo taken from the associated offsite tank battery location, facing East. Photo illustrates a List B Colorado noxious weed, Scotch thistle.



Photo 6. Close up photo taken of the remaining equipment.