

Final Reclamation Inspection

May 25, 2021

Operator: CONFLUENCE DJ LLC - #10518

Location ID: 320160

Inspection Document #: 697502963

Adams County, CO

SWSE Section 4 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PENROD 4-15 #1
Location ID: 320160



Photo 1. Photo taken from the entrance of the well location, facing North. Photo illustrates the road is evident and has not been reclaimed.

Inspection Photos
Location Name: PENROD 4-15 #1
Location ID: 320160



Photo 2. Photo taken from the well location, facing Northeast. Photo illustrates the well location is evident but it appears the location may have been recently seeded, along with the southern reference area. However, the seeding has not taken and is not reflective of reference areas.

Note: based on aerial imagery this pipe was placed after plugging operations.



Photo 3. Photo taken from the well location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: PENROD 4-15 #1
Location ID: 320160



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 5. Reference photo taken south of location, facing South.