

# *Inspection Photos*

*AL API#081-07660*

*Operator: POC-I*

*Insp#: 692403428*

*Insp Date: 5/21/2021*



Photo#1:

View over Location from entry to North.

May 21, 2021



Photo#2:  
Cathodic Protection unit.



Photo#3:  
Staining/leak at Cathodic Protection unit.

May 21, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: POC AL Iles Dome Unit API#081-07660





Photo#4:  
Site used as storage facility.



Photo#5:  
Site used as storage facility.

May 21, 2021



**Photo#6:**  
Stored supplies and unstable West side cut slope.



**Photo#7:**  
White Top (Noxious Weed) is established on East fill slope.

May 21, 2021