

Inspection Photos

API#081-06501

Operator: Stehle Oil

OWP

Insp#:692403433

Insp Date: 5/21/2021



Photo#1:
Overview of Location to Southwest.



Photo#2:
View of fill slopes to East from lease road.

May 21, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Stehle Iles Dome Co (OWP) API#081-06501



Photo#3:
View along fill slope to South.

Photo#4:
Well head; just completed P&A.

May 21, 2021



Inspection Photos: Stehle Iles Dome Co (OWP) API#081-06501