

Inspection Photos

Location Name: CAERUS PICEANCE LLC Orchard Unit /21-3 (F21OU)

Location ID: 415597



Photo #3984 from entrance to location.



Photo #3985 from entrance to location.



Inspection Photos

Location Name: CAERUS PICEANCE LLC Orchard Unit /21-3 (F21OU)

Location ID: 415597



Photo #3986 Location lacks stabilization.



Photo #3987 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Orchard Unit /21-3 (F21OU)

Location ID: 415597



Network: Jun 1, 2021 at 12:58:41 PM MD
Local: Jun 1, 2021 at 12:58:41 PM MD



Network: Jun 1, 2021 at 12:58:48 PM MD
Local: Jun 1, 2021 at 12:58:48 PM MD

Photo #3988 No form of tracking BMP located at entrance to location.

Photo #3989 No battery sign located at the tank battery.