

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



Photo #3991 from entrance to location.



Photo #3992 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



Photo #3161 from inspection #699802775 conducted on 3/16/21.



Photo #3993 Location lacks stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



**Photo #3166 from inspection #699802775 conducted on 3/16/21.**



**Photo #3994 Location lacks stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



**Photo #3995 No form of tracking BMP at entrance to location.**