

Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



Photo #3997 from entrance to location.



Photo #3998 No battery sign located at the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources