

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2021

Submitted Date:

06/02/2021

Document Number:

700702839

FIELD INSPECTION FORM

Loc ID 383338	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 11 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
302066	WELL	PR	01/01/2014	GW	045-18355	GMU 26-12A2 (L26NW)	PR
302067	WELL	PR	04/12/2011	GW	045-18356	GMU 27-9A (L26NW)	PR
302068	WELL	PR	02/01/2011	GW	045-18357	GMU FEE 27-10D2 (L26NW)	PR
302069	WELL	PR	05/09/2011	GW	045-18358	GMU 27-9D1 (L26NW)	PR
302070	WELL	PR	02/01/2011	GW	045-18359	GMU 27-9C (L26NW)	PR
302071	WELL	PR	02/01/2011	GW	045-18360	GMU 27-9D2 (L26NW)	PR
302072	WELL	PR	09/10/2010	GW	045-18361	GMU FEE 27-16A (L26NW)	PR

General Comment: COGCC Inspection Report Summary On Tuesday 6/1/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus L26NW, at Location # 383338 in Garfield county Colorado. While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	302066	Type:	WELL	API Number:	045-18355	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	302067	Type:	WELL	API Number:	045-18356	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	302068	Type:	WELL	API Number:	045-18357	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	302069	Type:	WELL	API Number:	045-18358	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	302070	Type:	WELL	API Number:	045-18359	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	302071	Type:	WELL	API Number:	045-18360	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	302072	Type:	WELL	API Number:	045-18361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Culverts				
Berms						
		Ditches				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702844	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445362