

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<u>Adequate</u>		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	<u>Unused tote north of the separator needs to be removed for good housekeeping. See attached photo.</u>		
Corrective Action:	<u>Comply with Rule 606.</u>	Date:	<u>06/11/2021</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	<u>Barbwire</u>		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	<u>Barbwire</u>		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	<u>Barbwire</u>		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	1- not in use 1- needs to be calibrated before returning to production.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.316700,-104.475000
Comment:					
Corrective Action:					Date:

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 479961 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 6/2/21 at approximately 0823hrs, I, Inspector Adam Burns, Conducted an on-site inspection at 18-4N-63W NENE Sater Watkins TB of Noble Energy, at Facility ID #479961 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unused tote north of the separator needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 6/11/21. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	06/02/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103779	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445560