

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2021

Submitted Date:

06/02/2021

Document Number:

699103798

FIELD INSPECTION FORMLoc ID 305956 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284044	WELL	SI	02/01/2021	GW	123-23736	SPIKE STATE CC 30-23	TA

General Comment:

This is a follow up to FIRR #402699385. CA has been corrected.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 284044 Type: WELL API Number: 123-23736 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 04/14/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 6/2/21 at approximately 1136hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402699385 at Spike State CC 30-23 of Noble Energy, at Location ID# 305956 in Weld County, Colorado.</p> <p>During this inspection the compliance issue has been corrected to comply with COGCC rules.</p> <p>See attached photos.</p> <p>This is a summary of inspection report.</p>	burnsa	06/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103799	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445569