

Inspection Photos
Operator: Simcoe
API: 067-09019
Date: 5/28/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with intermediate wheatgrass, western wheatgrass, crested wheatgrass, rubber rabbitbrush, and sand dropseed.



Photos 3. View of the southern project area from the southwestern corner facing eastward.



Photos 4. View of musk thistles within the project area. Approximately 25 individuals observed.



Photo 5. View of reference area vegetation comprised of sagebrush shrubland with scattered pinyon and juniper trees, as well as squirreltail, western wheatgrass, phlox, and penstemon in the understory.