

Inspection Photos
Operator: Simcoe
API: 067-06613
Date: 5/28/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Weed debris from tumble weeds observed within the project area.



Photos 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area, comprised of irrigated grass field.