

# Final Reclamation Inspection

May 27, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 328616

Inspection Document #: 697502976

Weld County, CO

NWNE Section 5 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: KUIS #C 5-02  
Location ID: 328616



**Photo 1.** Photo taken from the associated offsite tank battery location, facing West. Photo illustrates all equipment has been removed and the location was recently mowed. The establishment and desirable perennial vegetation was observed but has not reached reference area vegetative levels.



Inspection Photos  
Location Name: KUIS #C 5-02  
Location ID: 328616



**Photo 2.** Photo taken from the associated offsite tank battery location, facing Southwest.  
See comments under Photo 1.



Inspection Photos  
Location Name: KUIS #C 5-02  
Location ID: 328616



**Photo 3.** Photo taken from the associated offsite tank battery location, facing South. See comments under Photo 1.

