

# Final Reclamation and Stormwater Inspection

May 27, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 330924

Inspection Document #: 697502978

Weld County, CO

SWSW Section 5 T4N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources<sub>S</sub>

Inspection Photos  
Location Name: WYSCAVER #5-14  
Location ID: 330924



**Photo 1.** Photo taken from the eastern well location, facing Southwest. Photo illustrates Operator has fenced off access road and well location. Operator performed interseeding in already established areas that did not have uniform vegetative plant cover.



**Photo 2.** Photo taken from the eastern well location, facing Northwest. See comments under Photo 1.



Inspection Photos  
Location Name: WYSCAVER #5-14  
Location ID: 330924



**Photo 3.** Photo taken from the northern well location, facing Southeast. Photo illustrates Operator performed final reclamation activities by seeding and mulching reclamation areas. Germination of desirable plant species was observed throughout the reclamation areas.



**Photo 4.** Photo taken from the northern well location, facing South. See comments under Photo 3.



Inspection Photos  
Location Name: WYSCAVER #5-14  
Location ID: 330924



**Photo 5.** Photo taken from the southern well location access road, facing Northeast. See comments under Photo 3.



**Photo 6.** Photo taken from the southern well location access road, facing Southeast. See comments under Photo 3.



Inspection Photos  
Location Name: WYSCAVER #5-14  
Location ID: 330924



**Photo 7.** Photo taken from the associated offsite tank battery location, facing South. Photo illustrates the tank battery has been fenced off. See comments under Photo 3.



**Photo 8.** Photo taken from the associated offsite tank battery location, facing Southwest. See comments under Photo 7.