

Final Reclamation and Stormwater Inspection

May 27, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 331561

Inspection Document #: 697502980

Weld County, CO

NESW Section 5 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources_S

Inspection Photos
Location Name: WYSCAVER 23-5
Location ID: 331561



Photo 1. Photo taken from PDC's shared portion of the tank battery, facing West. Operator performed final reclamation activities by seeding and mulching reclamation areas. Germination of desirable plant species was observed throughout the reclamation areas.



Photo 2. Photo taken from PDC's shared portion of the tank battery, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: WYSCAVER 23-5
Location ID: 331561



Photo 3. Photo taken from the eastern well location access road, facing Northeast. Photo illustrates Operator has fenced off access road and well location.



Photo 4. Photo taken from the eastern well location access road, facing North. See comments under Photo 3.

Inspection Photos
Location Name: WYSCAVER 23-5
Location ID: 331561



Photo 5. Photo taken from a portion of the well location access road, facing North. See comments under Photo 3.



Photo 6. Photo taken from the western well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: WYSCAVER 23-5
Location ID: 331561



Photo 7. Photo taken from the western well location, facing North. See comments under Photo 3.



Photo 8. Photo taken from the western well location, facing Southeast. See comments under Photo 1.