

Final Reclamation and Stormwater Inspection

May 27, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 331801

Inspection Document #: 697502982

Weld County, CO

NWSW Section 5 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources_S

Inspection Photos
Location Name: WYSCAVER #13-5
Location ID: 331801



Photo 1. Photo taken from the southeastern well location, facing West. Photo illustrates Operator has fenced off access road and well location. Operator performed interseeding in already established areas that did not have uniform vegetative plant cover. Where there was little or no establishment, Operator seeded and mulched those reclamation areas. Germination of desirable plant species was observed throughout the reclamation areas.



Photo 2. Photo taken from the southeastern well location, facing Northwest. See comments under Photo 1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502980

Inspection Photos
Location Name: WYSCAVER #13-5
Location ID: 331801



Photo 3. Photo taken from the southeastern well location, facing North. See comments under Photo 1.



Photo 4. Photo taken from the southeastern well location, facing South. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502980

Inspection Photos
Location Name: WYSCAVER #13-5
Location ID: 331801



Photo 5. Photo taken from the northern well location, facing East. See comments under Photo 1.



Photo 6. Photo taken from the northern well location, facing South. See comments under Photo 1.

