

Final Reclamation and Stormwater Inspection

May 27, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 331802

Inspection Document #: 697502984

Weld County, CO

SESW Section 5 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources₅

Inspection Photos
Location Name: WYSCAVER #24-5
Location ID: 331802



Photo 1. Photo taken from a portion of the well location access road, facing Northeast. Photo illustrates Operator has fenced off access road and well location. Operator performed interseeding in already established areas that did not have uniform vegetative plant cover. Where there was little or no establishment, Operator seeded and mulched those reclamation areas. Germination of desirable plant species was observed throughout the reclamation areas.

Inspection Photos
Location Name: WYSCAVER #24-5
Location ID: 331802



Photo 2. Photo taken from a portion of the well location access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: WYSCAVER #24-5
Location ID: 331802



Photo 3. Photo taken from a portion of the well location access road, facing Southeast. See comments under Photo 1.