

Koda Exploration, LLC.
Roaring Fork 14-28
SESW, Sec. 28, T16S, R54W, 6th PM
Pit Remediation and Sampling Photo Log

Photo 1



Pit prior to mixing facing southwest 5/15/21

Photo 2



Pit prior to mixing facing west 5/15/21

Photo 3



Pit after mixing facing northwest 5/15/21

Photo 4



W01 sample location facing west 5/19/21

Photo 5



N01 sample location facing north 5/19/21

Photo 6



E01 sample location facing east 5/19/21

Photo 7



S01 sample location facing south 5/19/21