



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

SW Rangely 14-18-1-2

API: 05-103-09516

Inspection: 701500926



39.95566, -108.88889, 6135.1ft, 294°
06/02/2021 11:28:35 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Tank.

SW Rangely 14-18-1-2

API: 05-103-09516

Inspection: 701500926



39.95566, -108.88898, 6132.7ft, 254°
06/02/2021 11:28:48 AM