

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2021

Submitted Date:

06/03/2021

Document Number:

689805847

FIELD INSPECTION FORM

Loc ID 313190 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10559
Name of Operator: SOUTHLAND ROYALTY COMPANY LLC
Address: 400 WEST 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gallenbeck, Danny		dgallenbeck@ctfieldsvcs.com	
Elgin, Jerry		jelgin@mspartner.com	
Blaylock, Connie		cblaylock@mspartner.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271331	WELL	SI	12/29/2010	GW	081-07173	BAKERS PEAK UNIT 2	WK

General Comment:

Routine FIU inspection. Inspector on location to witness portion of PA. Form 6 document number 402639848.

Inspected Facilities

Facility ID: 271331 Type: WELL API Number: 081-07173 Status: SI Insp. Status: WK

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 1500-1300

Cement Volume (sx): 23

Good Return During Job: YES

Cement Type: Class G 15.8

Comment: Inspector on location to witness portion of plugging. Inspector observed pumping of plug between 1500-1300. 23 sxs of class G cement, weight 15.8. Good returns.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689805848	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5446660