

Inspection Photos
John Weigandt Consolidation
Spill ID 465402 (AC)



Photo 1 – Spill excavation. Fencing up around open excavation.



Photo 2 – Spill excavation.

Inspection Photos
John Weigandt Consolidation
Spill ID 465402 (AC)



Photo 3 – Spill excavation. Trash in open excavation.



Photo 4 – Excavation has expanded to removed stained soils previously observed on the surface.

Inspection Photos
John Weigandt Consolidation
Spill ID 465402 (AC)



Photo 5 – Trash in open excavation.



Photo 6 – Trash in open excavation.

Inspection Photos
John Weigandt Consolidation
Spill ID 465402 (AC)



Photo 7 – Trash on location.



Photo 8 – Trash in open excavation.