

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2021

Submitted Date:

06/06/2021

Document Number:

696104623

**FIELD INSPECTION FORM**

Loc ID 451060 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

22 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451059	WELL	PR	05/30/2019	OW	123-44958	Wells Ranch BB09-649	PR
451061	WELL	PR	04/27/2018	OW	123-44959	Wells Ranch BB11-658	PR
451062	WELL	PR	05/27/2019	OW	123-44960	Wells Ranch BB09-654	PR
451063	WELL	PR	04/01/2018	OW	123-44961	Wells Ranch BB11-650	PR
451064	WELL	PR	04/28/2018	OW	123-44962	Wells Ranch BB11-643	PR
451065	WELL	PR	05/31/2019	OW	123-44963	Wells Ranch BB09-650	PR

**General Comment:**

This is a WELL inspection.  
Well(s): 6: Producing | PR.  
Battery: Active.

Centralized Battery serves 3 Location IDs  
(451073, 451045, 451060).  
(Well(s): 18: Producing | PR).

Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	6: Wellsites.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Methanol, Corrosion Inhibitor.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	6: Wellsites. Iron panel.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Gas lift manifolds. Iron pipe.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 6		corrective date

Comment:	6: Gas lift allocation meters: Calibration card indicates calibration within last year. Last calibration: 08/27/2020. Active.		Date:
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:	6: Wellsites. Appears plumbed to surface.		Date:
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:	6: Wellsites.		Date:
Corrective Action:			Date:
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.		Date:
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	At wellsites: 2: Corrosion Inhibitor pumps, tanks w/ drip containment. Placarded. 3: Methanol pumps, tanks w/ drip containment. Placarded.		Date:
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.416167,-104.411952
Comment:	Centralized Battery serves 3 Location IDs (451073, 451045, 451060).  Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	Date:
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>451059</u>	Type: <u>WELL</u>	API Number: <u>123-44958</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing   PR.</u>			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: <u>10/20/2020</u>		Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results		Initial Surf Csg Pressure: <u>0</u>	Fluid Type: _____
		End Surf Csg Pressure: <u>0</u>	
Comment: _____		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>451061</u>	Type: <u>WELL</u>	API Number: <u>123-44959</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing   PR.</u>			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: <u>06/04/2020</u>		Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results		Initial Surf Csg Pressure: <u>6</u>	Fluid Type: _____
		End Surf Csg Pressure: <u>0</u>	
Comment: _____		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>451062</u>	Type: <u>WELL</u>	API Number: <u>123-44960</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing   PR.</u>			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: <u>03/17/2021</u>		Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results		Initial Surf Csg Pressure: <u>0</u>	Fluid Type: <u>NONE</u>
		End Surf Csg Pressure: <u>0</u>	
Comment: _____		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>451063</u>	Type: <u>WELL</u>	API Number: <u>123-44961</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing   PR.</u>			
Corrective Action:		Date:	

**BradenHead**

Date of Last Brhd Test: 06/03/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 451064 Type: WELL API Number: 123-44962 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/03/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 451065 Type: WELL API Number: 123-44963 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/01/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 100 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 06/04/2021 at approximately 15:49 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: BB11-12 /Pad                      Location ID: 451060                      Well Name(s): Wells Ranch BB09-649, Wells Ranch BB11-658, Wells Ranch BB09-654, Wells Ranch BB11-650, Wells Ranch BB11-643, Wells Ranch BB09-650.                      API: 05-123-44958, 05-123-44959, 05-123-44960, 05-123-44961, 05-123-44962, 05-123-44963.                      Location County: Weld County, Colorado                      Weather: Sunny, dry.</p> <p>While there, I observed:                      Well(s): 6: Producing   PR.                      Battery: Active.</p> <p>Centralized Battery serves 3 Location IDs (451073, 451045, 451060).                      (Well(s): 18: Producing   PR).</p> <p>Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/06/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104624	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5448242">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5448242</a>