

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2021

Submitted Date:

06/06/2021

Document Number:

696104625**FIELD INSPECTION FORM**

Loc ID 451045	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> <div style="border: 1px solid black; padding: 2px;"> 24 Number of Comments  0 Number of Corrective Actions  <input type="checkbox"/> Corrective Action Response Requested </div>
<b>Operator Information:</b> OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>1001 NOBLE ENERGY WAY</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77070</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451046	WELL	PR	06/04/2019	OW	123-44948	Wells Ranch State BB09-617	PR
451047	WELL	PR	05/09/2018	OW	123-44949	Wells Ranch BB11-627	PR
451048	WELL	PR	08/01/2020	OW	123-44950	Wells Ranch BB11-618	PR
451050	WELL	PR	05/09/2018	OW	123-44951	Wells Ranch BB11-635	PR
451051	WELL	PR	06/04/2019	OW	123-44952	Wells Ranch BB09-639	PR
451052	WELL	PR	06/04/2019	OW	123-44953	Wells Ranch BB09-626	PR

<b>General Comment:</b> This is a WELL inspection. Well(s): 6: Producing   PR. Battery: Active.  Centralized Battery serves 3 Location IDs (451073, 451045, 451060). (Well(s): 18: Producing   PR).  Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.
--

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type				
Comment:	Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	6: Wellsites.			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Methanol, Corrosion Inhibitor.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	OTHER			
Comment:	Gas lift manifolds. Iron pipe.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	6: Wellsites. Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Ancillary equipment	# 5			corrective date
Comment:	At wellsites: 2: Corrosion Inhibitor pumps, tanks w/ drip containment. Placarded. 3: Methanol pumps, tanks w/ drip containment. Placarded.			

Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	6: Gas lift allocation meters: Calibration card indicates calibration within last year. Last calibration: 08/27/2020. Active.		
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	6: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	6: Wellsites.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.416167,-104.411952
Comment:	Centralized Battery serves 3 Location IDs (451073, 451045, 451060).  Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: 451046	Type: WELL	API Number: 123-44948	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: <span style="color: blue;">Producing   PR.</span>			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 10/06/2020		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	
Facility ID: 451047	Type: WELL	API Number: 123-44949	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: <span style="color: blue;">Producing   PR.</span>			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 05/21/2020		Annual Brhd Completed? No	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: <span style="color: blue;">No record of Brhd test within last 12 months. Submit current Brhd test per Rule 207.</span>			
Corrective Action:		Date:	
Facility ID: 451048	Type: WELL	API Number: 123-44950	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: <span style="color: blue;">Producing   PR.</span>			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 12/02/2020		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type: NONE
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	
Facility ID: 451050	Type: WELL	API Number: 123-44951	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: <span style="color: blue;">Producing   PR.</span>			
Corrective Action:		Date:	

**BradenHead**

Date of Last Brhd Test: 06/04/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 451051 Type: WELL API Number: 123-44952 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 03/05/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 451052 Type: WELL API Number: 123-44953 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/30/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:

End Surf Csg Pressure: 0

Comment: No record of Brhd test within last 12 months.  
Submit current Brhd test per Rule 207.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 06/04/2021 at approximately 16:17 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: BB11-13/Pad  Location ID: 451045  Well Name(s): Wells Ranch State BB09-617, Wells Ranch BB11-627, Wells Ranch BB11-618, Wells Ranch BB11-635, Wells Ranch BB09-639, Wells Ranch BB09-626.  API: 05-123-44948, 05-123-44949, 05-123-44950, 05-123-44951, 05-123-44952, 05-123-44953.  Location County: Weld County, Colorado  Weather: Sunny, dry.</p> <p>While there, I observed:  Well(s): 6: Producing   PR.  Battery: Active.</p> <p>Centralized Battery serves 3 Location IDs (451073, 451045, 451060).  (Well(s): 18: Producing   PR).</p> <p>Refer to Field Inspection Report doc. #696104621 and/or Location ID #451073 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/06/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104626	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5448243">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5448243</a>