

Inspection Photos

API: 073-06113

Operator: CITATION OIL & GAS CORP

Inspection Date: 6/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 1. Facing east along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 2. Facing north along the road which was required to be reclaimed. There are areas along the former road where desirable vegetation has not established and there is undesirable weed growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 3. Facing northeast at the location. The location consists predominately of undesirable weeds which has to be controlled. The location has not re-established a desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 4. Facing east at the location. The location consists predominately of undesirable weeds and there are areas with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 5. Facing north at the location. The location consists predominately of undesirable weeds which has to be controlled. The location has not re-established a desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 6. Facing west at the location. The location consists predominately of undesirable weeds and there are areas with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 7. Facing south at the location. The location consists predominately of undesirable weeds which has to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



Photo 8. View of ground cover shows undesirable weeds (Kochia sp.) which was observed throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021

Inspection Photos



06.02.2021

Photo 9. Facing west toward the undisturbed surrounding rangeland which consists of Blue grama, Sand dropseed among other native vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06113 | Date: 6/2/2021