

**Inspection Photos**  
**Operator: Logos Operating**  
**API: 067-06250**  
**Date: 6/3/2021**



Photo 1. View of project area from the northwestern corner facing center.



Photo 2. View of riser that remains within the project area and needs removal.



Photos 3. View of tank that remains in the southern project area, needs removal.



Photos 4. View of reference area comprised of big sagebrush and black sagebrush shrubland with mosaic of cleared grass field with smooth brome and crested wheatgrass.