

Inspection Photos
Location Name: Duncan Unit 1 3
Location ID: 313036



Photo 1. Overview of location taken facing west.



Inspection Photos
Location Name: Duncan Unit 1 3
Location ID: 313036



Photo 2. No bradenhead access apparent.



Photo 3. Stained soil on location.

