

**Inspection Photos**  
**Location Name: Hiawatha 3**  
**Location ID: 313118**



**Photo 1. Overview of location taken facing northwest.**



**Photo 2. No bradenhead access apparent. Dried annual weeds at wellhead. Stained soil at wellhead.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources